Weathertzetton-Assistance Program

Work Order Bid (ID)

WORK ORDER INFORMATION

Work Order Name: WO/17017UC-0823/1

Work Order Type: Weatherization

Audit Name: 17017UC-0823

CLIENT INFORMATION

Client ID: 17017UC-0823

AGENCY INFORMATION

Client ID: 17017UC-0823

Agency:Upper Cumberland H R AAgency Phone:(931) 528-1127

Fax:

Address: 3313 Williams Enterprise Drive

Cookeville, TN 38506 Email Address:

Company Name & License Number:	
Contractor's Signature:	

<u>COMMENT</u>

Measures

ı	Measure 1	Fix I Fan	Not Operational Bathrod	om Exha	ust	Componer	nts		ı	Inspected
C	omment RE	PLA	CE EXSISTING FAN/ LIG	HT						
						Estimated	d		Actual	
#	Material / Lab	oor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified		Misc Material	Each	1					
C	Other Detail									
					Measur	e Sub Total:] .	Sub Total:	
	Field Notes:					<u>'</u>				
	Measure 2 comment RE		or Repair 12 SQ. FT CE PLYWOOD UNDER F	RENCH	DOOR	Componer HOLE IN F	LOOR		I Actual	Inspected
#	Material / Lab	or	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Miscellaneou		Plywood / 32sqft	SqFt	1]		
	Supplies		,	·						
2	Miscellaneou	IS	Plywood w/ Joist Repair	SqFt	1					
	Supplies		/ 32sqft							
	Other Detail									
					Measur	e Sub Total:]	Sub Total:	
Γ	Field Notes:									
	rielu Notes:									

Measure 3	Seal Ducts			Componen	its		į	Inspected
REF SEA SEA	CTS: {{DUCTS EXTREMLY PLACE INSULATE FLEXIBL AL/ REPAIR 9 DUCTS WITH AL/ CAULK INSIDE RETURN /ITY	E DUCT 1 MASTIC	5 FT			VALL		
				Estimated	<u> </u>		Actual	
# Material / Labo	or Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Duct sealing (setup cost)	Each	1					
10 Miscellaneous Supplies	Duct Sealing	Each	1					
Other Detail								
			Measur	e Sub Total:] ,	Sub Total:	
Measure 4	General Air Sealing			Componen	its		,	Inspected
Comment INF	•			E NDITION				Inspected
Comment INF	ILTRATION: INDARD HOUSE DOOR FO OR IS LEAKY AND IN DETE	ERIORATE	D CON	E NDITION Estimated	1		Actual	
Comment INF STA DOG	ILTRATION: INDARD HOUSE DOOR FOOD IS LEAKY AND IN DETE	ERIORATE <i>Units</i>	D CON	E NDITION		Qty		Inspected
Comment INF	ILTRATION: INDARD HOUSE DOOR FO OR IS LEAKY AND IN DETE	ERIORATE	D CON	E NDITION Estimated	1	Qty	Actual	
Comment INF STA DOG	ILTRATION: ANDARD HOUSE DOOR FOODR IS LEAKY AND IN DETENT OF Description / Comment General air sealing (setup cost)	ERIORATE <i>Units</i>	D CON	E NDITION Estimated	1	Qty	Actual	
# Material / Laboration 10 Miscellaneous	ILTRATION: ANDARD HOUSE DOOR FOODR IS LEAKY AND IN DETENT OF Description / Comment General air sealing (setup cost)	ERIORATE <i>Units</i> Each	Qty	E NDITION Estimated	1	Qty	Actual	
# Material / Laboration 1 Insulation 1 Miscellaneous Supplies	ILTRATION: ANDARD HOUSE DOOR FOODR IS LEAKY AND IN DETENT OF Description / Comment General air sealing (setup cost)	ERIORATE <i>Units</i> Each	Qty	E NDITION Estimated	1	Qty	Actual	
# Material / Laboration 1 Insulation 1 Miscellaneous Supplies	ILTRATION: ANDARD HOUSE DOOR FOODR IS LEAKY AND IN DETENT OF Description / Comment General air sealing (setup cost)	ERIORATE <i>Units</i> Each	Qty	E NDITION Estimated	1	Qty	Actual	
# Material / Laboration 1 Insulation 1 Miscellaneous Supplies	ILTRATION: ANDARD HOUSE DOOR FOODR IS LEAKY AND IN DETENT OF Description / Comment General air sealing (setup cost)	Units Each Each	O CON Qty 1	E NDITION Estimated	1		Actual	Total
# Material / Laboration 1 Insulation 1 Miscellaneous Supplies	ILTRATION: ANDARD HOUSE DOOR FOODR IS LEAKY AND IN DETENT OF Description / Comment General air sealing (setup cost)	Units Each Each	O CON Qty 1	E NDITION Estimated Unit Cost	1		Actual Unit Cost	
# Material / Labo 1 Insulation 10 Miscellaneous Supplies Other Detail	ILTRATION: ANDARD HOUSE DOOR FOODR IS LEAKY AND IN DETENT OF Description / Comment General air sealing (setup cost)	Units Each Each	O CON Qty 1	E NDITION Estimated Unit Cost	1		Actual Unit Cost	

	Measure 5 Set	back [heating] a tune - up!!			Componen	ts			Inspected
-		1			Estimated	,		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Heating Equipment	Setback thermostat	Each	1					
2	Labor	Setback thermostat	Each	1					
0	ther Detail						1		
] []	Sub Total:	
				weasur	e Sub Total:		,	Sub Total.	
	Measure 6 DW Omment	H Pipe Insulation			Componen			,	Inspecte
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DWH Pipe Insulation	Each	1					
2	Labor	DWH Pipe Insulation	Each	1					
0	ther Detail] [
] []		
]	Sub Total:	
				Measur	e Sub Total:		'	Sub Total:	
	Field Notes:								

Measure 7 Bel	ly Cellulose Loose			Componen	ts			Inspected
Comment mobile	home underbelly & r-19 f	iberglass f	or 1248	3 sq. ft				
		Estimated Actual						
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
3 Other	Floor Insulation - Celluls,Blwn	Each	1					
Other Detail						_		
			Measur	e Sub Total:] ,	Sub Total:	
Measure 8 DW Comment	H Tank Insulation			Componen	ts			Inspected
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DWH Tank Insulation	Each	1					
2 Labor			1					
Other Detail	DWH Tank Insulation	Each	1					
Other Detail	DWH Tank Insulation	Eacn	'					
Other Detail	DWH Tank Insulation	Each	·					
Other Detail	DWH Tank Insulation	Each						
Other Betain	DWH Tank Insulation			e Sub Total:			Sub Total:	

Measure 9 Smoke Detector is Needed					Componen	its		Inspected		
C	Comment									
					Estimated	<u> </u>		Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1	Health and Safety Items	9-volt Smoke Detector	Each	1						
2	Labor	Labor	Hour	1						
(Other Detail						,			
				Measur	e Sub Total:			Sub Total:		
Ī	Field Notes:									
L										
			Work Or	der Gra	nd Total:		Gran	d Total:		